

Oil Field Environmental Incident Summary

Incident: 20160526111834 **Date/Time of Notice:** 05/26/2016 11:18

Responsible Party: Oneok Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Stateline Gas Plant

Field Name:

Well File #:

Date Incident: 5/26/2016 **Time Incident:** 08:30

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 103

Sec: 21

Qtr: SE

Location Description: 15071 56th Street NW
Williston, ND 588011

Submitted By: Levi Weltikol

Received By:

Contact Person: Levi Weltikol
896 25th St SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	3	Gallons				

Description of Other Released Contaminant:

Liquid Propane

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk

Areal Extent:

Potential Environmental Impacts:

No environmental impacts

Action Taken or Planned:

Operator tightened packing bolts which stopped the release and set up containment. impacted soil will be removed. reporting as exempt because the product was still in the process and not to storage yet.

Wastes Disposal Location: Certified Landfill

Agencies Involved:

Updates

Date: 5/27/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release at a non-exempt E&P facility. Follow-up is required.

Date: 6/9/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arranged with rep that follow-up will coincide with quarterly inspections.